

Government Response to RFCs

15) Question: We are unable to locate the thickness of the windows on the referenced drawings. In order to get pricing for the new windows, we need to know glass thickness. Can this be provided?

Answer: The drawing showing window thickness is now available. Please see Attachment-8 Amendment 0004 Drawings and References.

16) Question: SOW States: A person qualified as weld inspector per AWS QC1 shall accomplish a visual inspection consisting of hull integrity, deck assessment, structural components to include keel, frames and bulkheads, seaworthiness, ABYC standards compliance and recommendations. In conversations with multiple entities (CWI & Engineers), the feedback we have received is that it is not clear what the intention of the SOW requirement is. Can you clarify which ABYC standard specifically the requirement is calling out? (ABYC standards typically do not apply to hull integrity). Can you provide any clarifying information on what the baseline is for the inspection criteria?

Answer: This RFC is currently under review. The Government intends to provide a response before the end of the solicitation.
