

ATTACHMENT TO QUESTION 20 -AMENDMENT 0005

Existing Hydro / Renewable Energy Control Equipment Photographs

Rehabilitation of the Eielson Visitor Center
Denali National Park and Preserve, Alaska
Reference: Drawing U101

Reference Note: These photographs are provided to show observed existing equipment within the Utility Building. They are informational and do not identify every component or connection shown on Drawing U101. Existing equipment configuration and connections, including the FAA DC connection, shall be field verified.



Photo 1 - Utility Building equipment overview. The red circles identify the left-side equipment group and the upper-right enclosure referenced in the following photographs. The red wall phone visible between the equipment groups was reportedly intended for communication with the turbine house; operational status has not been verified.



Photo 2 - Interior of the upper-left equipment enclosure, as identified in the A/E field notes. Specific equipment function and existing connections shall be field verified.




Photo 3 - Interior of the lower-left equipment enclosure / field-voltage-control equipment, as identified in the A/E field notes. Specific equipment function and existing connections shall be field verified.



Photo 4 - Upper-right enclosure labeled "HYDRO METER." The interior of this enclosure was not photographed.